



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 18, 2008

Supervisor TR

Mine Name: Vermillion Mine	Permit Number: S/053/0076
Operator Name: Color Country Rock, LLC	Inspection Date: April 9, 2008
Inspector(s): Lynn Kunzler	Time: 10:30 am
Other Participants: Russell Shriener, BLM	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

Disturbance at this site appears to be approaching 5 acres. There was evidence that there has been recent activity on the site, although no activity was occurring during this inspection. It was noted that there has been some topsoil salvaged and stockpiled at the site. The site was clean, and no erosion problems noted (light rain during inspection). The site appears to be in compliance. The site is currently bonded (bond held by BLM - LOC for \$15,000).

Photos were taken to document site conditions.

Conclusions and Recommendations:

Continue to monitor the site when in the area.

Inspector's Signature [Signature]

LK:pb

cc: Preston Hafen, Operator
Russell Shriener, BLM

O:\M053-Washington\S0530071-Windy\Inspections\Insp-04092008.doc

080001